



Submitted Comment on Transmission Development Forum

California Public Utilities Commission comments on the January 2026 Transmission Development Forum.

1. On the Vaca Dixon Area Reinforcement (Install 2 Capacitor Banks in which a Flicker study resulted in a change to cap bank configuration and, in turn, requiring four additional circuit breakers, please provide more information. This seems like a great deal of disruption and delay caused by flicker. What alternatives were considered and why was this alternative chosen?