

TECHNICAL BULLETIN

Import Limit Definition and Management in Support of Under-Frequency Load Shedding (UFLS)

December 3, 2009

(Updated on December 17, 2012)

(Updated on September 30, 2013. Limit to be removed on October 1, 2013)

Author: ISO/MQRI/NL



Revision History

Date	Version	Description	Author
12/3/2012	1.0	Provided information regarding import	ISO
		limit definition and management	
12/17/2012	2.0	Removed branch group component list	ISO
09/30/2013	3.0	Limit is no longer needed starting on October 1, 2013.	ISO

Note: This technical bulletin is provided for the convenience of the market participant for the purpose of communicating complex and technical information. The technical bulletin is intended to be consistent with the ISO tariff, however, the ISO is bound to operate in accordance with the tariff in all cases. In the event there is any conflict between this technical bulletin and the ISO tariff, the ISO tariff will control. Any provision of the ISO tariff that may have been summarized or repeated in this technical bulletin is provided only to aid in the understanding of this technical bulletin and in no event shall any of the information in this technical bulletin be deemed an interpretation of the tariff, or in any way binding. While the ISO endeavors to update the information and analysis in this technical bulletin and to notify market participants of changes pertinent to this technical bulletin, it is the responsibility of each market participant to ensure that he or she is using the most recent version of this technical bulletin that it has not been retired or withdrawn, that the information in the technical bulletin is current, and to comply with all applicable provisions of the ISO's tariff. The market participant use of this technical bulletin, and all information contained herein, is at its sole risk.

www.caiso.com December 17, 2012

Author: ISO/MQRI/NL



SCE_PCT_IMP_BG is removed from the ISO real-time and day ahead markets effective on trade day October 1, 2013. This is to align with the removal of the under-frequency import limit to the SCE area.

The under-frequency import limit was enforced based on the Transmission Owners local reliability criteria under the Transmission Control Agreement. The limit was intended to maintain sufficient resource supply balance within an area under a severe under frequency load shedding and intertie separation event. The limit recognized the pre-ISO intertie under frequency separation scheme that would separate the SCE area at designed intertie points and intra-tie locations.

ISO and SCE recently conducted a joint study to evaluate the effectiveness of the existing Under Frequency Load Shedding and separation scheme and considered potential modifications to the separation scheme. The joint study result recommended that ISO and SCE (with coordination with other PTOs) make slight change in the UFLS intertie separation scheme. The UFLS intertie separation scheme works independently of the limit and the limit is not required for application of the scheme. The limit as previously applied by the ISO was necessary to ensure the ISO met the PTO requirements for managing their system reliably in the event of an under frequency event. However, in such cases, the UFLS protocols worked independent of the import limit, pursuant to WECC requirements. With the change on the UFLS intertie separation scheme targeted to be implemented in October 1, the under-frequency import limit that was based on the separation scheme to isolate SCE area in case of a under frequency separation event was deemed to no longer be necessary by the PTO and the ISO. Therefore, the import limit will be removed from the ISO's requirements.

The SCE_PCT_IMP_BG constraint will also be removed from the monthly CRR model starting with the November 2013 CRR process. However, the constraint is included in the 2014 annual CRR model since the annual process was already started in August. The SCE_PCT_IMP_BG limit will no longer be considered in the ISO transmission planning requirements.

This limit is not replaced by another limit and the ISO will not make operational adjustments to honor this limit.

www.caiso.com Page 3 of 5

Author: ISO/MQRI/NL